



MAHA Software Update


A new 2.1 Version of the ESP30970-18-R H8 Board requires an update to the MAHA software. New 2.1 Board pictured below



1. Boot Up into Windows and type CTRL+ALT+DEL and select Log Off
2. Login as FSR (or Opus for VA) with today's Password
3. Go to Start Menu and select Computer
4. Browse to the DVD Drive (or USB for VA) and double-click the folder Update
5. Double Click "MAHA_update.vbs"



6. Select OK to apply the update



7. Confirm the new version is 1.5.0.2, select OK to exit
8. Remove CD and launch SysTest software to run Dyne Calibrations